



## Cable Modem

[Status](#) [Signal](#) [Addresses](#) [Configuration](#) [Logs](#)

[Open Source](#) [Help](#)

This page displays detailed information intended for use by an authorized Motorola Corporation Cable Modem technician.

Time	Priority	Code	Message
Jan 01 1970 00:00:15	6-Notice	N/A	Cable Modem Reboot due to timeout ;CM-MAC=3c:36:e4:97:00:5c CMTS-MAC=00:00:00:00:00: CM-QOS=1.1;CM-VER=3.0;
Oct 16 2015 19:13:19	3-Critical	R04.0	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=3c:36:e4:97:00:5c; CMTS-MAC=00:01:5c:69:4c: CM-QOS=1.1;CM-VER=3.0;
Oct 16 2015 19:13:19	5-Warning	T202.0	Lost MDD Timeout;CM-MAC=3c:36:e4:97:00:5c; CMTS-MAC=00:01:5c:69:4c: CM-QOS=1.1;CM-VER=3.0;
Oct 16 2015 19:13:17	3-Critical	R04.0	Received Response to Broadcast Maintenance Request, But no Unicast Maintenance opportunities received - T4 time out;CM-MAC=3c:36:e4:97:00:5c; CMTS-MAC=00:01:5c:69:4c: CM-QOS=1.1;CM-VER=3.0;
Oct 16 2015 19:12:56	3-Critical	T05.0	SYNC Timing Synchronizatio failure - Loss of Sync;CM-MAC=3c:36:e4:97:00:5c; CMTS-MAC=00:01:5c:69:4c: